




**Wymiary prowadnic**



<b>A</b>	500	550	600	650	700	750	800	850	900	950	1000
<b>B±3</b>	500	550	600	650	700	750	800	850	900	950	1000

**Mocowanie prowadnic do korpusu**



**Mocowanie prowadnic do szuflady**

L	A	B	C	D	E	F
<b>500</b>	192	384	-	160	384	-
<b>550</b>	192	416	-	192	416	-
<b>600</b>	128	288	480	192	352	480
<b>650</b>	160	320	512	192	384	544
<b>700</b>	192	384	576	192	384	576
<b>750</b>	192	384	576	192	416	608
<b>800</b>	224	448	672	224	448	672
<b>850</b>	224	448	672	224	448	672
<b>900</b>	256	512	768	256	512	768
<b>950</b>	256	544	832	256	544	832
<b>1000</b>	288	576	864	288	576	864